



Technical Service Bulletin 061129

IOX / DCX Beam Control & CB3 Motor Operator Schematic

This service bulletin provides a schematic (PN# 453332) to aid an operator in troubleshooting Thomson IOX and DCX transmitter **Beam Control** and **CB3 Motor Operator** faults. This schematic is a supplement to the technical support documentation provided with your specific transmitter. Use caution and observe all safety guidelines when troubleshooting operational circuits.

Please contact the Comark Customer Service Department with any questions related to this document or for additional technical support.

Comark Communications LLC 104 Feeding Hills Road Southwick, MA 01077 U.S. A. (800) 345-9295 Attn: Customer Service www.comarktv.com

Rev A - 29 November 2006

