



Technical Service Bulletin 070727 IOX / DCX Millennium Cabinet Interlock Diagram

This service bulletin provides a **Cabinet Interlock Diagram** (PN# 453368) to aid an operator in troubleshooting Comark IOX and DCX Millennium transmitter faults. This diagram is a supplement to the technical support documentation provided with your specific transmitter. Use caution and observe all safety guidelines when troubleshooting operational circuits. Please contact the Comark Customer Service Department with any questions related to this document or for additional technical support.

Comark Communications LLC 104 Feeding Hills Road Southwick, MA 01077 U.S. A. (800) 345-9295 Attn: Customer Service www.comarktv.com

(attach 453368 schematic)

