

Technical Service Bulletin 030413

Replacement UHF Preamplicifier Cover

This service bulletin concerns all Comark television transmitters utilizing the ADAPT ATSC exciter.

Replacement preamplicifier power supply cover


In an effort to increase the reliability of its products, Comark has designed a new cover (P/N 37403358) for the ADAPT Preamplicifier module. This new cover features additional perforations along the top and bottom edges to increase convection cooling air flow through the power supply section of the unit. The RF section of the preamplicifier is unaffected. No special tools or adjustments are required to install the replacement cover.

Comark is providing replacement covers free-of-charge for all of its transmitter customers. To obtain a free cover, please send an e-mail with your name, station call letters, quantity required, and shipping address to swikcsfeedback@comarktv.com

You will need one cover for each ADAPT exciter you currently have in service. All ADAPT preamplicifier modules installed or replaced since June 2003 should already have the new cover in place.

For more information on ADAPT cooling see Service Bulletin 040625

New perforated cover
P/N 37403358



WARNING: The UHF preamplicifier may be hot upon removal from service. Allow unit to sufficiently cool before attempting modification.

NOTE: For units with ARTESYN brand supply, leave internal cover in place. CHEROKEE brand supply has no internal cover.

Comark Communications
104 Feeding Hills Road
Southwick, MA 01077 U.S.A.
(800) 345-9295
<http://www.comarktv.com>